

# General Environmental Incident Summary

**Incident:** 2027      **Date/Time Notice:** 8/28/2013      1000      **DEM Incident No:**

**Responsible Party:** Nabors Completion & Production Services, Co.

**Date Incident:** 8/24/2013

**Time Incident:**

**Duration:**

**County:** McKenzie

**Twp:** 152

**Rng:** 100

**Sec:** 20

**Qtr:**

**Lat:** 47.96484

**Long:** -103.51480

**Method:** Navigation quality GPS

**Location Description:** Latitude: 47.96483551622179 and Longitude: -103.51482317792579; Hwy 85 turn left go to CR29, turn left and go 9 miles; turn left and go 0.5 miles on lease road into site - 4 well pad Shermen-Newberry-Pingora-Pike.

**Submitted By:** Daniel Cusick

**Affiliation:**

**Address:**

**City:**

**State:**

**Zip:**

**Received By:**

**Contact Person:** Patrick Kellam  
13568 58th Street NW  
Williston, ND 58801

**Distance Nearest Occupied Building:** 5000 Feet

**Type of Incident:** Fire

**Description of Released Contaminant:** LSG-1, XL-10, PH-16L, Super OW3, OB-2, OB Breaker, OWS-CMB-6, OWS-SI8, diesel, tires, oil

**Volume Spilled:**

**Ag Related:** No

**EPA Extremely Hazardous Substance:** No

**Reported to NRC:** No

**Cause of Incident:**

A fire occurred at a well pad site during fracing operations. Water from fire company washed compounds onto ground.

**Risk Evaluation:**

Risk has been mitigated by removing fuels on site. No immediate hazards to human health.

**# of Fatalities:** 0

**# of Injuries:** 0

**Affected Medium:** 03 - soil

**Potential Environmental Impacts:**

Impacts are contained to well pad and soil is media of concern pending analysis.

**Action Taken or Planned:**

Spill from water was contained on site. Currently over 100,000 gallons of water mixed with constituents recovered and contained in frac tanks. Water will be profiled for disposal characterization. Soil will be evaluated and impacted soil will be removed for disposal.

**Wastes Disposal Location:** Indian Hills or Prairie Disposal LLC

**Agencies Involved:** NDDes, Local Fire Department, O&G Division

## Updates

---

**Date:** 8/28/2013    **Status:** Reviewed - Follow-up Required

**Author:** Harries, Alison

### Updated Volume:

#### Notes:

Well operator was Oasis Petroleum. Spill did migrate off-site for several hundred yards. OP sent an email update with this additional information.

Contact David Edwards for more details:

1001 Fannin | Suite 1500 | Houston, TX 77002

281.404.9437 Direct | 832.794.7932 Cell

281.404.9709 Fax

dedwards@oasispetroleum.com

---

**Date:** 5/13/2015    **Status:** Inspection

**Author:** Espe, Brady

### Updated Volume:

#### Notes:

I arrived at the site at 16:58 p.m. The weather was cloudy, 50°F, with the wind from the southeast 5-10 mph. The site currently has a dike surrounding it. The west side has a higher dike; runoff appears to be directed to the southeast corner. At the time of inspection, I did not see any issues with vegetation on the dikes or pasture area. No further followup needed at this time. 47.96602; -103.51371